CCR No. 97- 0598	**Logged Date** 04/14/97	**Rev.** -	**Request Type** CCR

Priority Routine [X] Urgent [ ] Emergency [ ]	**Affected Release** B	**Change Class** II

Title (description)

Define Release B.0 EDC DAAC HW Baseline

Documents Affected	**Source Nos** (RID, NCR, Action Item, GSFC CCR, etc.) **or Tech Reference**
None	None

RTM Change [ ]   **Start New Baseline** [ ]

Problem

EDC DAAC HW mapping to support B.0 site installation.

Proposed Solution

Review and approve attached files containing:

1. EDC DAAC B.0 HW diagram.

Impact Analysis:

Organizations Affected:

	BOO [ ]	Contracts [ ]	ECS Chief Eng [ ]	FOS [ ]	M&O [ ]
Procurement [ ]	QO [ ]	Rel. Dev [X]	Rel. A [ ]	Rel. C [ ]	SCDO Arch. [ ]
Science Off [ ]	Security [ ]	Subcontrct [ ]	Sys. Eng [ ]	Sys Verf Acpt [ ]	

Cost: None [X]   Small [ ]   Medium [ ]   Large [ ]

(Not exceeding $100,000) ($100,000 to $500,000)   (Over $500,000)

Schedule: None [ ]   Other

Additional LOC _____   Man-Months _____

Materials

Originator   C. Van Steenberg, Const. Ofc.   Charleen Vansteenberg _____

Signature   Date

Office   Const. Mgr.   Office Manager   Chip Schwartz _____

Signature   Date

Disposition   Approved [X]   Approved w/Comment [ ]   Forward [ ]   Disapproved [ ]

CCB Chairperson   Ramsey Billups _____

Signature   Date